

1-619  
San

OFFICE OF THE EXECUTIVE ENGINEER PWD DN. BONLI (H.Q.- SAWAI MADHOPUR)

Format-D

No:-

Date:-

### Building Safety Certificate

Sub. :- Regarding Safety Certificate of Education **Smt.Chand Devi Rural Development & Social Welfare Society, Rawasa Teh. Bonli Distt. Sawai Madhopur.**

Ref : - Depositing fee DD No.15042019 dated 15.04.2019 for Rs 6000/-


Sir,

It is to inform that above building has been inspected by Assistant Engineer PWD Sub Dn II Bonli as recommended vide letter No.28 dated 20.05.2019 On the basis of recommended by AEN & affidavit furnished by owner, it is to certify that this Building is safe for school activities.

This Certificate is valid for a period **3 Year** i.e. only, up to **27.05.2022** (date) subject to regular upkeep and satisfactory Annual maintenance by school owner.

Note :- This Certificate will stand void automatically, if the building is used for any other purpose other than the school activities at any time during the year.

Yours faithfully

  
(Ram Raj Meena)

Executive Engineer

PWD Dn. Bonli

H.Q.- Sawai Madhopur

Date:- 28/05/19

No:- 253-54

Copy to the forwarded to:-

1. Assistant Engineer PWD Sub Dn I Bonli with reference to your letter No.28 dated 20.05.2019
2. Smt.Chand Devi Rural Development & Social Welfare Society, Rawasa Teh. Bonli Distt. Sawai Madhopur.

Executive Engineer

PWD Dn. Bonli

प्रपत्र-स

चेक लिस्ट :- स्कूल भवन के सुरक्षा प्रमाण पत्र हेतु कनिष्ठ अभियन्ता/सहायक अभियन्ता द्वारा

- 1 भवन का प्रकार :-  अरि.सी.सी. पिलर पर निर्मित / भार वाहक-दिबसे-पर निर्मित
- 2 छत की प्रकार / स्थिति :-  अरि.सी.सी. की छत / पट्टियों की छत, सुदृढ़ / सामान्य / कमजोर
- 3 दीवारों का प्रकार / स्थिति :- पत्थर की चिनाई / ईंट की चिनाई, सुदृढ़ / सामान्य / कमजोर
- 4 फर्श का प्रकार / स्थिति :- सीमेंट का / बिट्टीफाईड टाइल का / सी.सी. टाइल का / कच्चा / सुदृढ़ / सामान्य / कमजोर
- 5 दरवाजों का प्रकार / स्थिति :- लकड़ी के / लोहे के / सुदृढ़ / सामान्य / कमजोर
- 6 छिडकियों का प्रकार / स्थिति :- लकड़ी के / लोहे के / सुदृढ़ / सामान्य / कमजोर
- 7 प्लास्टर का प्रकार / स्थिति :- सीमेंट का / चूने का / सुदृढ़ / सामान्य / कमजोर
- 8 विद्युत व्यवस्था का प्रकार / स्थिति :-  कन्ड्यूट वायरिंग / प्लास्टर में दबी हुई वायरिंग / सतह पर की हुई वायरिंग / सुदृढ़ / सामान्य / कमजोर
- 9 20 मीटर दायरे में हाईटेशन लाईन की स्थिति :-  हैं / नहीं हैं
- 10 अन्य विशेष तथ्य

28/20-5-2019

नाम मय हजूमर  
सहायक अभियन्ता  
कनिष्ठ अभियन्ता/सहायक अभियन्ता  
सा.नि.वि. खण्ड VI

चेक लिस्ट अधिशापी अभियन्ता, सा.नि.वि. खण्ड VI को सौंपी जा रही है।  
है। अतः उक्त भवन का सुरक्षा प्रमाण पत्र जारी करने हेतु अनुशंसा की जाती है।

नाम मय हजूमर  
सहायक अभियन्ता  
कनिष्ठ अभियन्ता/सहायक अभियन्ता  
सा.नि.वि. खण्ड VI  
(कार्यालय मोहर)  
बोली (स.मा.)

he

**SOGANI MAHILA MAHAVIDYALAYA**


**VILLAGE -RAWASA TEHSIL-BONLI**

**DISTT. - SAWAI MADHOPUR (RAJ.)**

**KHASARA NO. 19/1 TOTAL LAND AREA -17500 Sq.m.**

**CONVERTED LAND AREA 7200 Sq.m. SIZE W-80M L-90M**

**BUILT UP AREA 857.20 Sq.m.**



**CAJIBU BHANUKAR NENKARU**  
**ERTA ARCHITECT**  
P. No. 19/1, Rawasa, Tehsil Bonli, Distt. Sawai Madhopur, Rajasthan  
Ph: 9829010101

*Handwritten signature and date: 10/11/2017*

*Handwritten text: 10/11/2017, 10/11/2017, 10/11/2017*